Under Review Notification

Raised By: Vanessa Morel Product #: SK393M44121

Date: 2019.11.07 Product Name: BELT DRIVE TRANS PINION RUNOUT ALIGNEMEN

		"Y" or "N" Required for Each Part							t		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
SK393M44121	SK393M44121 Rev	Υ	Υ	Ν	Υ	Υ	Z	N	Ν	19-1226	See below

Description of Issue:

Issues stated on ADR (Napkin drawing, missing infos)

SK393M44121 must be put on HOLD in Plex

SK393M44121 Finish good stock can be use as is

All subs and parts can be use as is

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of OperationsChief EngineerProduction EngineersProduct Manager - Solutions ProviderDirector Quality AssuranceEngineering Project ManagersProduction PlannersSupply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene